	The state of the s	Δ
		Full Zeafle Slesphie
	16 August 1957	B-26 SERIAL No.
		المراق ال
	at an integrated	7712
	This document is part of an integrated	'
	file. If separated from the the seview.	
		- 47
		DOCUMENT NO. 012
		NO CHANGE IN CLASS.
		CLASS, CHANGED TO: TS S C
		NEXT REVIEW DATE: AUTH: HR 70-2 1980
	Attention:	DATE:
	1. As a result of our telephone call of this m	norning. I contacted
	1. As a lessit of our telephone can or this h	10111111159 1 001111110101
	He informed me that the re	
	this material prior to forwarding the requisiti	approval for furnishing ion to Ogden Air Force
	this material prior to forwarding the requisiting Base, Utah. The following items have been requested:	ion to Ogden Air Force
		ion to Ogden Air Force
0	Base, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation)	ion to Ogden Air Force
0	Base, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be installation)	ion to Ogden Air Force equired on the complete required on the complete
)	Base, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be installation) One socket assembly #4155968 (two sock quired or	equired on the complete required on the complete et assemblies to be re-
0	Base, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam # 5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support support bracket #4128221 (two support	equired on the complete required on the complete tet assemblies to be re- in the complete installation) ort brackets to be required
7	Pase, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam # 5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the contract.)	equired on the complete required on the complete et assemblies to be re- n the complete installation) ort brackets to be required complete installation)
	Pase, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support bracket #412821 (two support bracket #412	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required omplete installation) order to be sure that our he hoisting arrangement
	Pase, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support bracket #412821 (two support bracket #4128	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	Pase, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support bracket #412821 (two support bracket #412	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the color of the colo	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the color of the colo	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the color of the colo	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the color of the colo	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the color of the colo	equired on the complete required on the complete et assemblies to be re- n the complete installation) ort brackets to be required omplete installation) order to be sure that our he hoisting arrangement n these items for use will yours.
	Base, Utah. 2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam # 5125787 (two beams to be rinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the constallation will fit into the aircraft and that it will be suitable. Anything you can do to obtain be sincerely appreciated. Very truly to the suitable of the suitable of the suitable.	equired on the complete required on the complete ret assemblies to be re- n the complete installation) ort brackets to be required complete installation) order to be sure that our he hoisting arrangement n these items for use will
	2. The following items have been requested: One hoist # 5122277 (two hoists to be reinstallation) One beam #5125787 (two beams to be reinstallation) One socket assembly #4155968 (two sock quired or One support bracket #4128221 (two support on the color of the colo	equired on the complete required on the complete et assemblies to be re- n the complete installation) ort brackets to be required omplete installation) order to be sure that our he hoisting arrangement n these items for use will yours.

Declassified in Part - Sanitized Copy Approved for Release 2013/08/14 : CIA-RDP78-03624A001500010012-1